

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/20/2019

Submitted Date:

02/20/2019

Document Number:

679703056**FIELD INSPECTION FORM**
 Loc ID 315166 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email                        | Comment                   |
|--------------|--------------|------------------------------|---------------------------|
| CO, Western  | 303-876-7091 | whitingwesternco@whiting.com | Western slope inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 230357      | WELL | PR     | 10/01/2018  | GW         | 103-08019 | HILL 7-6      | PR          |

**General Comment:**

Follow up inspection to document FIR 679702769 and FIRR 401935289 for which corrective actions were resolved. Which included the tank capacity sign.

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 800-723-4608

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |           |       |  |
|--------------------|-----------|-------|--|
| <b>Fencing/:</b>   |           |       |  |
| Type               | PUMP JACK |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>             |     |       | corrective date |
| Type: Deadman # & Marked      | # 4 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Bird Protectors         | # 2 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Vertical Separator      | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Emission Control Device | # 1 |       |                 |

|                                   |   |       |
|-----------------------------------|---|-------|
| Comment:                          |   |       |
| Corrective Action:                |   | Date: |
| Type: Gas Meter Run               | # 1   |       |
| Comment:                          |   |       |
| Corrective Action:                |   | Date: |
| Type: Ancillary equipment         | # 2   |       |
| Comment:                          | One container of methanol with secondary containment and 1 container of propane |       |
| Corrective Action:                |   | Date: |
| Type: Pump Jack                   | # 1   |       |
| Comment:                          |   |       |
| Corrective Action:                |   | Date: |
| Type: Horizontal Heated Separator | # 1   |       |
| Comment:                          |   |       |
| Corrective Action:                |   | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type     | Tank ID | SE GPS                |
|--------------------|---|----------|----------|---------|-----------------------|
| PRODUCED WATER     | 1 | <50 BBLs | Open Top |         | 40.086720,-108.771290 |
| Comment:           |   |          |          |         |                       |
| Corrective Action: |   |          |          |         | Date:                 |

**Paint**

|                  |             |
|------------------|-------------|
| Condition        | Adequate    |
| Other (Content)  |             |
| Other (Capacity) | 400 gallons |
| Other (Type)     |             |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
| Date:              |          |                     |                     |             |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | 400 BBLs | STEEL AST |         | 40.086720,-108.771290 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         |                       |
| Date:              |   |          |           |         |                       |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

Inspector Name: Moran, Rick

|                    |          |                  |                 |          |                       |
|--------------------|----------|------------------|-----------------|----------|-----------------------|
| Earth              | Adequate | Walls Sufficient | Base Sufficient | Adequate |                       |
| Comment:           |          |                  |                 |          |                       |
| Corrective Action: |          |                  |                 |          | Date:                 |
| Contents           | #        | Capacity         | Type            | Tank ID  | SE GPS                |
| PRODUCED WATER     | 1        | 400 BBLs         | STEEL AST       |          | 40.086720,-108.771290 |
| Comment:           |          |                  |                 |          |                       |
| Corrective Action: |          |                  |                 |          | Date:                 |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |                       |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |                       |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |
| CRUDE OIL          | 1        | 300 BBLs            | STEEL AST           |             | 40.086810,-108.770540 |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

Venting:

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

Flaring:

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

|                             |                                      |                       |            |                  |
|-----------------------------|--------------------------------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |                                      |                       |            |                  |
| Facility ID: 230357         | Type: WELL                           | API Number: 103-08019 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |                                      |                       |            |                  |
| Comment:                    | pump jack idle at time of inspection |                       |            |                  |
| Corrective Action:          |                                      |                       |            | Date:            |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 | Compaction              |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 679703057    | inspection photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4740882">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4740882</a> |