

**Inspection Photos**  
**Location Name: Thornton 11C-HZ Production Pad**  
**Location ID: 431521**



**Sound meter**




**Compressor at battery (suspected noise source)**

## Inspection Photos

Location Name: Thornton 11C-HZ Production Pad

Location ID: 431521



Distance of sound meter

