

Location Name: Timka Resources, LTD – Theurer Farms 22-28 Tank Battery (OSP)

Inspection Date: 2/01/2019



Photo # - 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources, LTD – Theurer Farms 22-28 Tank Battery (OSP)
Inspection Date: 2/01/2019



Photo # - 2

Location Name: Timka Resources, LTD – Theurer Farms 22-28 Tank Battery (OSP)
Inspection Date: 2/01/2019



Photo # - 3



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources, LTD – Theurer Farms 22-28 Tank Battery (OSP)
Inspection Date: 2/01/2019



Photo # - 4

View southeast across former oil skim pit. Cage removed and test pits being dug



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources, LTD – Theurer Farms 22-28 Tank Battery (OSP)
Inspection Date: 2/01/2019



Photo # - 5

View southwest across former oil skim pit. Cage removed and test pits being dug



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources, LTD – Theurer Farms 22-28 Tank Battery (OSP)
Inspection Date: 2/01/2019



Photo # - 6

East wall and berm of former oil skim pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources