

Inspection Photos
Location Name: MGP A-3
API #: 05-071-06093
Insp. Doc. # 695100198



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: MGP A-3
API #: 05-071-06093
Insp. Doc. # 695100198

LOWEST
ELEVATION



PHOTO 3: ICE BUILDUP ON WELLHEAD APPEARS TO BE PRODUCED WATER FROM LEAKING ROD PACKING



PHOTO 4: PRODUCED WATER LEVEL IN PIT APPEARS TO BE VERY CLOSE TO FREEBOARD/ FREEBOARD MARKER NOT INSTALLED CORRECTLY