

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2019

Submitted Date:

02/21/2019

Document Number:

689702691**FIELD INSPECTION FORM**

Loc ID 424630	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 32 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424642	WELL	PR	08/08/2013	GW	045-20914	STORY GULCH 8504D-36 D36496	PR
424645	WELL	PR	05/14/2013	GW	045-20915	STORY GULCH 8504A-36 D36496	PR
424646	WELL	PR	08/23/2013	GW	045-20916	STORY GULCH 8507A-35 D36496	PR
424647	WELL	PR	09/12/2013	GW	045-20917	STORY GULCH 8502D-35 D36496	PR
424652	WELL	PR	09/14/2013	GW	045-20918	STORY GULCH 8512E-36 D36496	PR
424653	WELL	PR	08/08/2013	GW	045-20919	STORY GULCH 8504B-36 D36496	PR
424655	WELL	PR	07/12/2013	GW	045-20920	STORY GULCH 8513E-25 D36496	PR
424656	WELL	PR	08/21/2013	GW	045-20921	STORY GULCH 8507B-35 D36496	PR
424657	WELL	PR	08/28/2013	GW	045-20922	STORY GULCH 8512D-36 D36496	PR
424658	WELL	PR	06/14/2013	GW	045-20923	STORY GULCH 8515E-25 D36496	PR
424659	WELL	PR	08/08/2013	GW	045-20924	STORY GULCH 8504C-36 D36496	PR
424661	WELL	PR	09/12/2013	GW	045-20925	STORY GULCH 8502B-35 D36496	PR
424662	WELL	PR	11/14/2013	GW	045-20926	STORY GULCH 8513A-36 D36496	PR
424663	WELL	PR	07/12/2013	GW	045-20927	STORY GULCH 8502A-35 D36496	PR

424664	WELL	PR	05/14/2013	GW	045-20928	STORY GULCH 8515E-26 D36496	PR
424665	WELL	PR	11/14/2013	GW	045-20929	STORY GULCH 8513B-36 D36496	PR
424666	WELL	PR	05/01/2013	GW	045-20930	STORY GULCH 8513D-25 D36496	PR
424668	WELL	PR	08/21/2013	GW	045-20931	STORY GULCH 8507E-35 D36496	PR
424672	WELL	PR	09/12/2013	GW	045-20932	STORY GULCH 8502C-35 D36496	PR
424673	WELL	PR	07/03/2013	GW	045-20933	STORY GULCH 8504E-36 D36496	PR
424674	WELL	PR	11/01/2016	GW	045-20934	STORY GULCH 8515D-25 D36496	PR
424676	WELL	PR	08/28/2013	GW	045-20935	STORY GULCH 8512C- 36D36496	PR
424677	WELL	PR	09/03/2013	GW	045-20936	STORY GULCH 8512A-36 D36496	PR
424678	WELL	PR	08/22/2013	GW	045-20937	STORY GULCH 8507C-35 D36496	PR
424679	WELL	PR	06/14/2013	GW	045-20938	STORY GULCH 8515D-26 D36496	PR
424680	WELL	PR	11/14/2013	GW	045-20939	STORY GULCH 8513C-36 D36496	PR
424684	WELL	PR	03/01/2013	GW	045-20940	STORY GULCH 8512B-36 D36496	PR
424687	WELL	PR	08/29/2013	GW	045-20941	STORY GULCH 8502E-35 D36496	PR

**General Comment:**

[Routine FIU General Field Inspection](#)

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	424642	Type:	WELL	API Number:	045-20914	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424645	Type:	WELL	API Number:	045-20915	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424646	Type:	WELL	API Number:	045-20916	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424647	Type:	WELL	API Number:	045-20917	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424652	Type:	WELL	API Number:	045-20918	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424653	Type:	WELL	API Number:	045-20919	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424655	Type:	WELL	API Number:	045-20920	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424656	Type:	WELL	API Number:	045-20921	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	424657	Type:	WELL	API Number:	045-20922	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424658	Type:	WELL	API Number:	045-20923	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424659	Type:	WELL	API Number:	045-20924	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424661	Type:	WELL	API Number:	045-20925	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424662	Type:	WELL	API Number:	045-20926	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424663	Type:	WELL	API Number:	045-20927	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424664	Type:	WELL	API Number:	045-20928	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424665	Type:	WELL	API Number:	045-20929	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	424666	Type:	WELL	API Number:	045-20930	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424668	Type:	WELL	API Number:	045-20931	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424672	Type:	WELL	API Number:	045-20932	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424673	Type:	WELL	API Number:	045-20933	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424674	Type:	WELL	API Number:	045-20934	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424676	Type:	WELL	API Number:	045-20935	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424677	Type:	WELL	API Number:	045-20936	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	424678	Type:	WELL	API Number:	045-20937	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	424679	Type:	WELL	API Number:	045-20938	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	424680	Type:	WELL	API Number:	045-20939	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	424684	Type:	WELL	API Number:	045-20940	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	424687	Type:	WELL	API Number:	045-20941	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702692	Inspection 689702691 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742515">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742515</a>