

Location Name: Fritzler Resources, Inc. – Decker B Pit (109572) Spill ID 462238

Inspection Date: 2/15/2019



Photo # - 1

Water seeping from the foot of the production pit on the northeast corner



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Fritzler Resources, Inc. – Decker B Pit (109572) Spill ID 462238

Inspection Date: 2/15/2019



Photo # - 2

Water seeping from the foot of the production pit on the northeast corner, view north



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Fritzler Resources, Inc. – Decker B Pit (109572) Spill ID 462238  
Inspection Date: 2/15/2019



Photo # - 3

Water seeping from the foot of the production pit on the northeast corner, view north



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources