

## Inspection Photos

Location Name: WRD FEDERAL 30-22, ANT HILL UNIT 30-23

Location ID: 05-103-10042, 10137

Inspection: 679703075



**Photo 1. Location looking west.**



**Photo 2. Two unused deadman lying on ground.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources