

Inspection Photos

Loc#334573

Operator: Terra

Inspection Number: 692400705

Inspection Date: 2/20/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South.

February 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bosely Loc#334753



Photo#2:
Drainage diversion area.

February 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bosely Loc#334753



Photo#3:
BMPs installed.



Photo#4:
BMPs installed.

February 21,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Bosely Loc#334753



Photo#5:
BMPs installed.



Photo#6:
BMPs installed.

February 21,2019