

# Final Reclamation and Stormwater Inspection

February 13, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 336322

Inspection Document #: 674902582

Weld County, CO

SWSE Section 15 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /2N68W15  
Location ID: 336322



**Photo 1.** Photo taken from the access road looking into the location, facing North. Appears Operator has left the access road, cattle guard and gate.



**Photo 2.** Photo taken from the location, facing West. Several piles of vegetation debris and hay bales are on location.

Inspection Photos  
Location Name: KERR MCGEE /2N68W15  
Location ID: 336322



**Photo 3.** Photo taken from the location, facing West. Appears Operator has performed recent final reclamation activities with the evidence of drill rows and straw crimped mulch.



**Photo 4.** Photo taken from the well location, facing North. See comments from Photo 3.



Inspection Photos  
Location Name: KERR MCGEE /2N68W15  
Location ID: 336322



**Photo 5.** Photo taken from the location, facing Southeast. See comments from Photo 3.



**Photo 6.** Photo taken from the location, facing Southeast. See comments from Photo 3.