

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2019

Submitted Date:

02/25/2019

Document Number:

680304670

FIELD INSPECTION FORM

Loc ID 303899 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 75027
Name of Operator: ROSEWOOD RESOURCES INC
Address: 2101 CEDAR SPRINGS RD STE 1500
City: DALLAS State: TX Zip: 75201

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Torres, Azucena	970-848-2228 ext. 108	azucenatorres@rosewd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253767	WELL	PR	03/21/1995	GW	125-07645	JOE BROPHY 8-14	PR

General Comment:

[Routine Site Inspection FIR - SATISFACTORY](#)

Location

Lease Road:			
	Type Access		
	comment: AG land trail		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
	Comment: Satisfactory		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: Satisfactory		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:				corrective date
Type: Prime Mover	# 1			
	Comment: Electric motor			
Corrective Action:				Date:
Type: Vertical Separator	# 1			
	Comment:			
Corrective Action:				Date:
Type: Pump Jack	# 1			
	Comment:			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
	Comment:			
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 253767 Type: WELL API Number: 125-07645 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT