

**Inspection Photos**  
**Location Name: ANT HILL UNIT 12-33**  
**Location ID: 05-103-10234**  
**Inspection: 679703095**



**Photo 1. Location looking north.**



**Photo 2. Well head.**



## Inspection Photos

Location Name: ANT HILL UNIT 12-33

Location ID: 05-103-10234

Inspection: 679703095



**Photo 3. Lease road sign with incorrect operator & phone number.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources