

Inspection Photos
Location Name: WRD FEDERAL 19-31
Location ID: 05-103-10143
Inspection: 679703105



Photo 1. Location looking east.



Photo 2. Oily waste at base of crude oil tank.

Inspection Photos
Location Name: WRD FEDERAL 19-31
Location ID: 05-103-10143
Inspection: 679703105



Photo 3. Tank battery looking south. Oil staining on side of oil tank.



Photo 4. Tank battery looking north. Oil staining on side of oil tank.

Inspection Photos
Location Name: WRD FEDERAL 19-31
Location ID: 05-103-10143
Inspection: 679703105



Photo 5. Xylene / ethylbenzene container.



Photo 6. Xylene / ethylbenzene container leaking into secondary containment.