

Final Reclamation Inspection

February 21, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-20677

Inspection Document #: 682404559

Weld County, CO

SENE Section 8 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC




COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE 5519 #42-8
API: 05-123-20677



COGCC aerial imagery from 2017 illustrating Plugged and Abandoned (PA) locations (red circles), an Abandoned Location (orange circle), and an Abandoned tank battery (green circle). This inspection is for 123-20677 (yellow plus sign). Operator has failed to perform Final Reclamation at the well location and has failed to perform Final Reclamation on any of the associated PA access roads.

Inspection Photos
Location Name: STATE 5519 #42-8
API: 05-123-20677



Photo 1. Photo taken from the PA location, facing South. Operator has not performed Final Reclamation activities at the well location. There is no evidence to suggest that Final Reclamation activities were performed (e.g., drill rows, mulch, or any desirable vegetation) and there is no evidence that portions have been contoured back to pre-existing conditions.

Inspection Photos
Location Name: STATE 5519 #42-8
API: 05-123-20677



Photo 2. Photo taken from the PA location, facing North. Operator has not performed Final Reclamation activities along the former access road. See comments under Photo 1.