

Final Reclamation Inspection

February 21, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-20675

Inspection Document #: 682404561

Weld County, CO

NWNE Section 8 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC




COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE 5519 # 31-8
API: 05-123-20675



COGCC aerial imagery from 2017 illustrating Plugged and Abandoned (PA) locations (red circles), an Abandoned Location (orange circle), and an Abandoned tank battery (green circle). This inspection is for 123-20675 (yellow plus sign). Operator has failed to perform Final Reclamation at the well location and any of the associated PA access roads.

Inspection Photos
Location Name: STATE 5519 # 31-8
API: 05-123-20675



Photo 1. Photo taken from the southern PA location, facing North. Operator has not performed Final Reclamation activities at the well location. There is no evidence to suggest that Final Reclamation activities were performed (e.g., drill rows, mulch, or any desirable vegetation).

Inspection Photos
Location Name: STATE 5519 # 31-8
API: 05-123-20675



Photo 2. Photo taken from the PA well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: STATE 5519 # 31-8
API: 05-123-20675



Photo 3. Photo taken from the former PA access road , facing West. Operator has not performed Final Reclamation activities at the access road.