

Final Reclamation Inspection

February 21, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-20676

Inspection Document #: 682404563

Weld County, CO

NENE Section 8 T5N R63W


Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE 5519 #41-8
API: 05-123-20676



COGCC aerial imagery from 2017 illustrating Plugged and Abandoned (PA) locations (red circles), an Abandoned Location (orange circle), and an Abandoned tank battery (green circle). This inspection is for 123-20676 (yellow plus sign) and the Abandoned tank battery (yellow plus sign). Operator has failed to perform Final Reclamation at the well location, tank battery, and any of the associated PA access roads.

Inspection Photos
Location Name: STATE 5519 #41-8
API: 05-123-20676



Photo 1. Photo taken from the PA well location, facing East. Operator has not performed Final Reclamation activities at the well location. There is no evidence to suggest that Final Reclamation activities were performed (e.g., drill rows, mulch, or any desirable vegetation).

Inspection Photos
Location Name: STATE 5519 #41-8
API: 05-123-20676



Photo 2. Photo taken from the former PA access road, facing West. Operator has not performed Final Reclamation activities at the access road.

Inspection Photos
Location Name: STATE 5519 #41-8
API: 05-123-20676



Photo 3. Photo taken from the offsite tank battery, facing East. Operator has not performed Final Reclamation activities at the tank battery. This offsite tank battery location was associated with three wells.