

Inspection Photos
Location Name: Diemoz
Location: 419380



Sign does not meet Rule 210 standards. Photo taken on 10/10/18 FIR # 680200178

Sign does not meet Rule 210 standards. Photo taken on 2/20/19 FIR # 692700006

Inspection Photos
Location Name: Diemoz
Location: 419380



Hay stored on location. Photo taken on 10/10/18 FIR # 680200178



Hay stored on location. Photo taken on 2/20/19 FIR # 692700006



Inspection Photos
Location Name: Diemoz
Location: 419380



Equipment stored on location . Photo taken on 10/10/18 FIR # 680200178



Equipment stored on location. Photo taken on 2/20/19 FIR # 692700006

Inspection Photos
Location Name: Diemoz
Location: 419380



Stored Hay in close proximity to well head. Photo taken on 10/10/18 FIR # 680200178



Stored Hay in close proximity to well head. Photo taken on 2/20/19 FIR # 692700006

Inspection Photos
Location Name: Diemoz
Location: 419380



Equipment stored on location . Photo taken on 10/10/18 FIR # 680200178



Equipment stored on location. Photo taken on 2/20/19 FIR # 692700006