

Inspection Photo (s)
Last Dance 9-3
05-045-09418
Inspection # 689303364



Location Photo #1



Location Photo #2, Stained ground by separator.

Inspection Photo (s)
Last Dance 9-3
05-045-09418
Inspection # 689303364



Location Photo #3, condensate under bucket.