

Final Reclamation Inspection

February 21, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-20136

Inspection Document #: 682404565

Weld County, CO

NENW Section 8 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: STATE 5519 #21-8

API: 05-123-20136



COGCC aerial imagery from 2017 illustrating the Plugged and Abandoned (PA) location (red circle). Operator has failed to perform Final Reclamation on the associated PA access road. The offsite tank battery appears to be active and in use for other nearby wells.

Inspection Photos
Location Name: STATE 5519 #21-8
API: 05-123-20136



Photo 1. Photo taken from the PA well location, facing North. Appears the Operator has performed Final Reclamation activities at the well location with the evidence of drill rows and mulch. Operator shall continue to monitor and manage this Location until it meets Rule 1004 standards, including weed management.

Inspection Photos
Location Name: STATE 5519 #21-8
API: 05-123-20136



Photo 2. Photo taken from the southern PA well location, facing South. Operator has not performed Final Reclamation activities at the access road. There is no evidence that the access road has been recontoured.