

Final Reclamation Inspection

February 21, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-19822

Inspection Document #: 682404567

Weld County, CO

SWNW Section 8 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: STATE 5519 #12-8

API: 05-123-19822



COGCC aerial imagery from 2017 illustrating the Plugged and Abandoned (PA) location (red circle). Operator has failed to perform Final Reclamation at the well location and the associated access road. The offsite tank battery appears to be active and in use for other nearby wells.

Inspection Photos

Location Name: STATE 5519 #12-8

API: 05-123-19822



Photo 1. Photo taken from the entrance of PA well location access road, facing South. Operator has not performed Final Reclamation activities at the access road. There is no evidence that the access road has been recontoured.

Inspection Photos

Location Name: STATE 5519 #12-8

API: 05-123-19822



Photo 2. Photo taken from the PA well location, facing Southeast. Operator has not performed Final Reclamation activities at the well. There is no evidence to suggest that Final Reclamation activities were performed (e.g., drill rows, mulch, or any desirable vegetation).