

Inspection Photos

Location Name: SHUR VIEW-65N67W /3NWNW

Location #: 306134




Photo #1

Shur View 18-3 (05-123-24030) Wellsite

Plugged & Abandoned | PA

NOT cut & capped | Temporary Safety cap



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources