

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2019

Submitted Date:

02/27/2019

Document Number:

688401413**FIELD INSPECTION FORM**

Loc ID 414890 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414859	WELL	SI	01/01/2017	OW	123-30866	GUTTERSEN STATE D 16-32D	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 0		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:						
Corrective Action:						Date:

Paint

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 414859 Type: WELL API Number: 123-30866 Status: SI Insp. Status: TA

COGCC Comments

Comment	User	Date
Witnessed MIT. Starting pressure's beforetest Tbg psi 1, Csg psi 0, BH psi 0. Started test at approx 10:30 AM. Starting pressure 465, 5 min 463, 10 min 461, 15 min 460. This is prep for P&A.	silverr	02/27/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401414	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4747427