

Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444




Photo #1
Great Western 35-52 (05-123-30748) Wellsite
Shut-In | SI



Photo #2
Great Western 35-52 Battery
Shut-down

Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444



Photo #3
Great Western 35-52 Front tank berm area
Stained soil
from prev. FIR



Photo #4
Great Western 35-52 Front tank berm area
Stained soil
Appears mitigated

Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444



Photo #5
Great Western 35-52 Inside tank berm area
Stained soil
from prev. FIR




Photo #6
Great Western 35-52 Inside tank berm area
Stained soil
Appears mitigated



Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444



Photo #7
Great Western 35-52 Crude oil tank rear
Stained soil
from prev. FIR



Photo #8
Great Western 35-52 Crude oil tank rear
Stained soil
Appears mitigated

Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444



Photo #9
Great Western 35-52 Separator dog house
Stained soil
from prev. FIR



Photo #10
Great Western 35-52 Separator dog house
Stained soil
Appears mitigated

Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444



Photo #11
Great Western 35-52 Wellhead
Stained soil
from prev. FIR



Photo #12
Great Western 35-52 Wellhead
Stained soil
Appears mitigated

Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444



Photo #13
Great Western 35-52 H2O vault
Hatch - Open
from prev. FIR



Photo #14
Great Western 35-52 H2O vault
Hatch - Closed
Stain appears mitigated

Inspection Photos
Location Name: GREAT WESTERN /35-52
Location #: 414444



Photo #15
Great Western 35-52 Access Road
Ruts
from prev. FIR



Photo #16
Great Western 35-52 Access Road
Ruts
Appears mitigated