

Inspection Photos
Location Name: HILL RANCH 25-12V
API #: 05-071-07280
Insp. Doc. # 695100244



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: HILL RANCH 25-12V
API #: 05-071-07280
Insp. Doc. # 695100244



PHOTO 3: WELLHEAD IS IN DISREPAIR AND IS HELD TOGETHER WITH A RATCHET STRAP. I CAN HEAR PRESSURE ESCAPING FROM WELLHEAD.



PHOTO 4: UNUSED EQUIPMENT ON LOCATION (UNUDED RISER, POLISH ROD AND RODS.