

Inspection Photos

2/27/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 421859

Inspection Doc. Number: 682504542

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 421859



Photo 1: Photo taken from the west end of the location facing north. Location is abandoned. Photo shows no oil and gas disturbance appears to have been conducted.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 421859



Photo 2: Photo taken from the location facing east. Location is abandoned. Photo shows no oil and gas disturbance appears to have been conducted.



Photo 3: Photo taken from the location facing south. Location is abandoned. Photo shows no oil and gas disturbance appears to have been conducted.



Photo 4: Photo taken from the location facing west. Location is abandoned. Photo shows no oil and gas disturbance appears to have been conducted.