

Inspection Photos

2/27/2019

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 428753

Inspection Doc. Number: 682504552
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southwest end of the location, facing north Photos 1-3 provide an overview of the interim and production areas of the location north, northeast, to east

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428753



Photo 2: See comments under photo 1.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428753



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the south end of the location, facing east. Photo shows portions of the interim area that do not appear to be progressing towards reclamation requirements. These areas will likely require additional reclamation activities.