

Inspection Photos

2/27/2019

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 428750

Inspection Doc. Number: 682504554
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 1: Photo taken from the east end of the location, facing south Photos 1-4 provide an overview of the interim and production areas of the location south, southwest, northwest, to north.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 2: See comments under photo 1.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 3: See comments under photo 1.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 4: See comments under photo 1.



Photo 5: Photo taken from the north end of the location, facing north. Photo show interim areas that remain predominantly bare and exposed soil, and have not achieved uniform vegetative cover. These areas will likely require additional reclamation activities to be conducted for reclamation to progress.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 6: Photo taken from the north end of the location, facing northeast. See comments under photo 5.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 7: Photo taken from the north end of the location, facing north. See comments under photo 5.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 8: Photo taken from the south end of the location, facing east. See comments under photo 5.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 428750



Photo 9: Photo taken from the south end of the location, facing east. See comments under photo 5.



Photo 10: Photo taken from the north end of the location, facing west. Photo shows a tank stored on location. Tank is not within secondary containment in accordance with 906.d(1)