

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2019

Submitted Date:

02/28/2019

Document Number:

692601501**FIELD INSPECTION FORM**

Loc ID 303034 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa | | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 252310 | WELL | PR | 06/01/2015 | GW | 125-06180 | ALLEN-SCHOBE 1-7 | PR |

General Comment:Routine Inspection

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through pasture | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Lease sign for associated wells mounted to meter shed | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead, VGS and meter shed | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 3 | | |
| Comment: | Shared meter run for (Allen/Schobe 1-7, Allen 32-7, Schobe 42-7) | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 3 | | |
| Comment: | 3-Vertical gas separators 50% buried by meter shed | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry equipment | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------|----|--|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 252310 | Type: | WELL | API Number: | 125-06180 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (Allen/Schobe 1-7, Allen 32-7, Schobe 42-7) @ 39.81496/-102.22557 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT