

## Inspection Photos

Location Name: RANGELY SOUTH 21-3-1-102

Location ID: 05-103-08968

Inspection: 679703148



Photo 1. Location looking north.




Photo 2. Operator and phone number labels peeling off.



## Inspection Photos

Location Name: RANGELY SOUTH 21-3-1-102

Location ID: 05-103-08968

Inspection: 679703148



**Photo 3. Two uncapped risers.**

