

Inspection Photos
Location Name: STATE-66N67W /36SEnw
Location #: 322743



Colorado Oil & Gas Conservation Commission
40.44436, -104.84511, 1423.0m, 219°
2019/02/28 02:50:00 PM


Photo #1
State 6-36, 7-36, 8-36 Tank Battery
State M 36-3, M 36-5
Shut-down



Colorado Oil & Gas Conservation Commission
40.44458, -104.84509, 1411.0m, 317°
2019/02/28 02:49:19 PM

Photo #2
State 6-36, 7-36, 8-36 Separator, GSM, ECDs
State M 36-3, M 36-5
Shut-down
Unused Equipment – Automation

Inspection Photos
Location Name: STATE-66N67W /36SENW
Location #: 322743



Colorado Oil & Gas Conservation Commission
40.44446, -104.8455, 1420.0m, 325°
2019/02/28 02:40:00 PM

Photo #3
State 7-36 (05-123-11980) Wellsite
Temporarily Abandoned | TA
Unused Equipment
Orange Decommission tag NOT present



Photo #4
State 6-36, 7-36, 8-36 Separator Area
State M 36-3, M 36-5
Unused Gas meter run
from prev. FIR



Inspection Photos
Location Name: STATE-66N67W /36SENW
Location #: 322743



Photo #5
State 6-36, 7-36, 8-36 Separator Area
State M 36-3, M 36-5
Unused Gas meter run line / riser
from prev. FIR



Photo #6
State 6-36, 7-36, 8-36 Separator Area
State M 36-3, M 36-5
Unused Gas meter run / riser
Have been removed

Inspection Photos
Location Name: STATE-66N67W /36SENW
Location #: 322743



Photo #7
State 7-36 Wellsite
Stained soil
from prev. FIR



Photo #8
State 7-36 Wellsite
Stained soil
Appears Remediated