

Inspection Photos
Location Name: STATE-66N67W /36NWNE
Location #: 322742



Photo #1
State 6-36 (05-123-11979) Wellsite
Temporarily Abandoned | TA
Unused Equipment
from prev. FIR



Photo #2
State 6-36 Wellsite
Temporarily Abandoned | TA
Unused Equipment - Removed
Orange Decommission tag NOT present



Inspection Photos
Location Name: STATE-66N67W /36NWNE
Location #: 322742



Photo #3
State 6-36, 7-36, 8-36 Tank Battery
State M 36-3, M 36-5
Shut-down



Photo #4
State 6-36, 7-36, 8-36 Separator, GSM, ECDs
State M 36-3, M 36-5
Shut-down