

## Inspection Photos

Location Name: Boies Ranch C-240 Pad and Remote Frac Line Spill

Location ID: #335678 Spill/Release ID #462832

Inspection Date: January 31, 2019



Photo #1 – Well pad signs.



Photo #2 – View of frac line, looking southeast





## Inspection Photos

Location Name: Boies Ranch C-240 Pad and Remote Frac Line Spill

Location ID: #335678 Spill/Release ID #462832

Inspection Date: January 31, 2019



Photo #3 – View of frac line, looking northwest.



Photo #4 – View of spill location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Boies Ranch C-240 Pad and Remote Frac Line Spill

Location ID: #335678 Spill/Release ID #462832

Inspection Date: January 31, 2019



**Photo #5 – View of irrigation ditch downstream from spill location, looking northwest.**



**Photo #6 – View of earthen berm and absorbent booms installed at terminus of spill path, looking west. Note proximity to Black Sulphur Creek.**



## Inspection Photos

Location Name: Boies Ranch C-240 Pad and Remote Frac Line Spill

Location ID: #335678 Spill/Release ID #462832

Inspection Date: January 31, 2019



**Photo #7 – View of inadequate chemical storage on pad. Operator was contacted via phone on 1/31/2019 and instructed to address spill within 24 hours.**



**Photo #8 - View of inadequate chemical storage on pad. Operator was contacted via phone on 1/31/2019 and instructed to address spill within 24 hours.**

## Inspection Photos

Location Name: Boies Ranch C-240 Pad and Remote Frac Line Spill

Location ID: #335678 Spill/Release ID #462832

Inspection Date: January 31, 2019



**Photo #9 – Fluid accumulations inside of cuttings area.  
Operator was contacted via phone 1/31/2019 and instructed  
to comply with cuttings management COAs.**



**Photo #10 – Cuttings storage area on pad.**

