

Inspection Photos
Location Name: LORENCITO 10-2
API #: 05-071-07123
Insp. Doc. # 695100241



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos

Location Name: LORENCITO 10-2

API #: 05-071-07123

Insp. Doc. # 695100241



**PHOTO 3: DISCHARGE LINE BYPASSING SEPARATOR/
IMPACTED SOIL NEAR WELLHEAD.**

PHOTO 4: PRODUCED WATER DISCHARGE POINT.

