

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2019

Submitted Date:

03/01/2019

Document Number:

689702763

**FIELD INSPECTION FORM**

Loc ID 335667 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282296	WELL	PR	08/03/2006	GW	045-11726	N PARACHUTE WF06C-23 F23596	PR
291476	WELL	PR	01/31/2009	GW	045-14383	N PARACHUTE WF12D-23 F23596	PR
291501	WELL	PR	07/31/2008	GW	045-14427	N PARACHUTE WF14C-23 F23596	PR
291502	WELL	PR	07/23/2007	GW	045-14426	N PARACHUTE WF15A-23 F23596	PR
291503	WELL	PR	01/31/2009	GW	045-14425	N PARACHUTE WF05C-23 F23596	PR
291505	WELL	PR	02/01/2012	GW	045-14423	N PARACHUTE WF11D-23 F23596	PR
291506	WELL	PR	07/08/2009	GW	045-14422	N PARACHUTE WF06D-23 F23596	PR
291508	WELL	PR	04/11/2012	GW	045-14421	N. PARACHUTE WF 14A-23F23596	PR
291512	WELL	PR	03/01/2009	GW	045-14419	N PARACHUTE WF12A-23 F23596	PR
291514	WELL	PR	07/23/2007	GW	045-14418	N PARACHUTE WF14B-23 F23596	PR
291523	WELL	AL	05/27/2011	LO	045-14416	ENCANA RPW 411-23-596	AL
291525	WELL	PR	01/01/2009	GW	045-14414	N PARACHUTE WF11B-23 F23596	PR
291527	WELL	PR	07/23/2007	GW	045-14412	N PARACHUTE WF11A-23 F23596	PR
291529	WELL	PR	01/19/2009	GW	045-14410	N PARACHUTE WF12B-23 F23596	PR

291530	WELL	PR	04/01/2012	GW	045-14408	N PARACHUTE WF11C-23 F23596	PR
--------	------	----	------------	----	-----------	--------------------------------	----

**General Comment:**

[Routine FIU General Field Inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No NFPA sticker on 1 tank and unlegible sticker on another.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	05/03/2019

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Capacity	Type	Tank ID	SE GPS	corrective date
Type: Plunger Lift	# 15					
Comment:						
Corrective Action:					Date:	
Type: Horizontal Heated Separator	# 20					
Comment:						
Corrective Action:					Date:	
Type: Bird Protectors	# 11					
Comment:						
Corrective Action:					Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	282296	Type:	WELL	API Number:	045-11726	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291476	Type:	WELL	API Number:	045-14383	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291501	Type:	WELL	API Number:	045-14427	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291502	Type:	WELL	API Number:	045-14426	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291503	Type:	WELL	API Number:	045-14425	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291505	Type:	WELL	API Number:	045-14423	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291506	Type:	WELL	API Number:	045-14422	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291508	Type:	WELL	API Number:	045-14421	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 291512	Type: WELL	API Number: 045-14419	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291514	Type: WELL	API Number: 045-14418	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291523	Type: WELL	API Number: 045-14416	Status: AL	Insp. Status: AL
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291525	Type: WELL	API Number: 045-14414	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291527	Type: WELL	API Number: 045-14412	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291529	Type: WELL	API Number: 045-14410	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 291530	Type: WELL	API Number: 045-14408	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
Berms	Pass					
Compaction	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702764	Inspection 689702763 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751187">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751187</a>