

Inspection Photos
Location Name: Trindle #2
Location ID: 307049



Crude oil tank placards on 11/26/18



Crude oil tank placards on 3/4/2019

Inspection Photos
Location Name: Trindle #2
Location ID: 307049



Unused water tank next to crude oil tank on 11/26/18



Unused water tank removed on 3/4/2019

Inspection Photos
Location Name: Trindle #2
Location ID: 307049



Wellhead on 11/26/18



Bradenhead valve on 3/4/2019