

## Inspection Photos

Location Name: AC McLAUGHLIN 83X

Location ID: 05-103-10595

Inspection: 679703207



**Photo 1. Location looking northeast.**



**Photo 2. Inhibitor pump leaking fluid outside of secondary containment.**

