

Inspection Photos

Location Name: GRAY B-17

Location ID: 05-103-05825

Inspection: 679703218



Photo 1. Location looking east.



Photo 2. Unmarked deadman.