

Construction and Stormwater Inspection

February 21, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 456174

Inspection Document #: 682404582

Weld County, CO

Lot 3 Section 7 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BB /07-33 PAD
Location ID: 456174



Photo 1. Photo taken from the northern well pad, facing West. Photo illustrates the topsoil stockpile that has been temporarily stabilized with hydromulch. In addition, Operator shall ensure topsoil is protected from weed establishment.

Inspection Photos
Location Name: BB /07-33 PAD
Location ID: 456174



Photo 2. Photo taken from the northeastern entrance to location, facing East. Photo illustrates outlet protection for a culvert installed in conjunction with a ditch and berm which is directed to a retention area.



Photo 3. Photo taken from the northeastern entrance to location, facing Northeast. See comments under Photo 2.

Inspection Photos
Location Name: BB /07-33 PAD
Location ID: 456174



Photo 4. Photo taken from the eastern well pad, facing East. See comments under Photo 1.

Inspection Photos
Location Name: BB /07-33 PAD
Location ID: 456174



Photo 5. Photo taken from the southeastern well pad, facing North. Photo illustrates a retention area with a stabilized outlet. Hydromulch has also been applied within the retention area.

Inspection Photos
Location Name: BB /07-33 PAD
Location ID: 456174



Photo 6. Photo taken from the southeastern well pad, facing West. Photo illustrates the southern topsoil stockpile- see comments under Photo 1. Photo also illustrates the ditch and berm BMP with a stabilized inlet for the culvert which is directed to a retention area.