

Final Reclamation Inspection

February 21, 2019

Operator: NOBLE ENERGY INC- #100322

API: 05-123-12701

Inspection Document #: 682404584

Weld County, CO

SESE Section 12 T5N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SLW #2-12
API: 05-123-12701



Photo 1. Photo taken from the eastern area of the former plugged and abandoned location on 12/24/2018, facing West. Well was plugged on 6/1/2015. Operator has failed to perform final reclamation activities (decompact, contour, remove gravel, etc.) per Rule 1004 standards.



Photo 2. Photo taken from the eastern area of the former plugged and abandoned location on 2/21/2019, facing West. Appears the Operator is in-process of performing Final Reclamation activities.