

Inspection Photos

Location Name: Wilkinson 19-24 (66N66W /19SENW)

Location #: 332498 (API: 05-123-22381)



Wellhead sign on 12/26/2017

Photo #1

Wilkinson 19-24 (05-123-22381) Wellsite

Shut-In| SI

Sign: Well Name – Incorrect
from prev. FIR




Photo #2

Wilkinson 19-24 Wellsite

Plugged & Abandoned | PA

Sign appears Correct

NOT Cut & Capped – Temp. cap appears in place

Unused Equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources