

Inspection Photos

Location Name: THAYER-66N66W /19NESW

Location #: 332501



Photo #1

Thayer 19-31 (05-123-22385) Wellsite

Plugged & Abandoned | PA

NOT Cut & Capped – Temp. cap appears in place

Unused Equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources