

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/01/2019

Submitted Date:

03/05/2019

Document Number:

680304671

FIELD INSPECTION FORM
 Loc ID 337514 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 7950 JOHN T WHITE ROAD

City: FORT WORTH State: TX Zip: 76120

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286409	WELL	PR	02/01/2015	GW	125-10294	WALCHLE 3-27-5-43	PR

General Comment:

Routine Site Inspection FIR

Note to Operator: Update production reports.

Location

Lease Road:			
Type	Access		
comment:	Grassland/Range		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Satisfactory

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Satisfactory		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	286409	Type:	WELL	API Number:	125-10294	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	GW								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment:

Use BMP's for erosion management

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT