

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2019

Submitted Date:

03/05/2019

Document Number:

680304677

FIELD INSPECTION FORM

Loc ID 337511 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 66190
Name of Operator: OMIMEX PETROLEUM INC
Address: 7950 JOHN T WHITE ROAD
City: FORT WORTH State: TX Zip: 76120

Contact Information:

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286372	WELL	PR	09/03/2008	GW	125-10291	WALCHLE 5-27-5-43	PR

General Comment:

[Routine Site Inspection FIR](#)
[Note to Operator: Update production reports](#)

Location

Lease Road:

	Type Access		
comment:	Grassland/Range		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 286372 Type: WELL API Number: 125-10291 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT