

Inspection Photos

Location Name: COUNTRY 1-66N66W /29NWNW

Location #: 310450



Photo #1

Country 1 29-4 (05-123-26421) Wellsite

Temporarily Abandoned | TA

Unused Equipment

Orange Decommission tag NOT present



Inspection Photos

Location Name: COUNTRY 1-66N66W /29NWNW

Location #: 310450



Photo #2
Country 1 29-4 Battery
Unused Equipment
from prev. FIR



Photo #3
Country 1 29-4 Battery
Shut-down
Unused Equipment - Removed

