


**PIT STATUS EVALUATION FORM**  
 Facility ID: 115057  
 Pit Name: DAUGHENBAUGH 26-2

Duplicate Record(s) Pit #

115147



**Legend**

- Database Pit Location
- Producing Well
- + Shut In Well
- ⊕ Temp Aban Well
- ⊗ Abandoned Well
- ⊙ Dry & Aban Well
- ◆ Injection Well
- Other Well Status



1:6,000




Image Source:  
 USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: GARY-WILLIAMS OIL PRODUCER INC  
 T: 6S R: 64W Sec: 26 QQ: NWNE 6th Meridian  
 Latitude: 39.504147 Longitude: -104.521016 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

- Active  Form 15: Pit Permit (1986) existing Assoc. Well Seq No(s) \_\_\_\_\_  
 Other documentation \_\_\_\_\_  
 Aerial photo verification \_\_\_\_\_
- Closed  Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice \_\_\_\_\_  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
 Well API Seq #(s) 06368 PA  
 Other documentation WSIF # 448169 (6-7-1988)
- Abandoned  Possible un-reclaimed pit(s) or adverse conditions, no closure docs  Site Visit  
 Unknown  No Site Visit  Add'l Review

Notes: WSIF pits backfilled & site clean (1988)  
documents for Pit # 115147 indicate NWNE Sec 26 but X,Y coordinates show  
pit in NENE coordinate - edit location of #115147 (IF for ID# 115147 (1987) indicates  
askim tank plus pit.