

The remaining section of flow line has remained in place due to vicinity of other lines.

about 5' of flow line was remove at the time of the C&C.

The Badding 9-35sx C&C is complete.

