

Inspection Photo (s)
Savage RWF 524-28
API # 05-045-17198
FIR Inspection # 689303436



Location Photo #1



Location Photo #2

Inspection Photo (s)
Savage RWF 524-28
API # 05-045-17198
FIR Inspection # 689303436



Location Photo #3



Location Photo #4, Unused/unmarked flow line near Separators.

Inspection Photo (s)
Savage RWF 524-28
API # 05-045-17198
FIR Inspection # 689303436



Location Photo #5, Access road is washed out.



Location Photo #6, Access road is washed out.

Inspection Photo (s)
Savage RWF 524-28
API # 05-045-17198
FIR Inspection # 689303436



Location Photo #7, Access road is washed out.



Location Photo #8, Access road is washed out.

Inspection Photo (s)
Savage RWF 524-28
API # 05-045-17198
FIR Inspection # 689303436



Location Photo #9, Access road is washed out.



Location Photo #10, Rilling on the access road.