

Inspection Photo (s)
Cook RMV 77-33
API # 05-045-07087
FIR Inspection # 689303444



Location Photo #1



Location Photo #2

Inspection Photo (s)
Cook RMV 77-33
API # 05-045-07087
FIR Inspection # 689303444



Location Photo #3, Debris on location.



Location Photo #4, unused/unmarked flow line.