

# Construction and Storm Water Inspection

February 26, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC – 10110

Location ID: 452180

Inspection Document #: 674902625

Weld County, CO

NWNW Section 1 T3N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



**Photo 1.** Photo taken from the northwestern perimeter of the location, facing South. Photo illustrates a compacted BMP that has been installed around the perimeter of the location.



**Photo 2.** Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 1.

## Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



**Photo 3.** Photo taken from the western perimeter of the location, facing Southeast. Photo illustrates the topsoil stockpile being stored along the southern area.



**Photo 4.** Photo taken from the southwestern perimeter of the location, facing South. A ditch and berm BMP was being installed around the topsoil pile at the time of the inspection and have not been completed due to lack of compaction and has not been installed with best engineering practices. However this should have been complete at the time of inspection because major dirt work activities had already been completed.



## Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



**Photo 5.** Photo taken from the southern perimeter of the location, facing East. Photo illustrates the topsoil stockpile being stored along the southern area is not stabilized . See comments from Photo 4.



**Photo 6.** Photo taken from the southeastern perimeter of the location, facing West. See comments from Photos 4 and 5.

## Inspection Photos

Location Name: GREAT WESTERN OPERATING – 100322/3N68W1

Location ID: 452180



**Photo 7.** Photo taken from the southeastern perimeter of the location, facing North. See comments from Photo 4.



**Photo 8.** Photo taken from the northeastern perimeter of the location, facing South. See comments from Photo 1.