

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2019

Submitted Date:

03/06/2019

Document Number:

696100380

**FIELD INSPECTION FORM**

Loc ID 305922 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	
		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283713	WELL	SI	10/08/2018	OW	123-23684	KREYKES 13-15	TA

**General Comment:**

This is a WELL Inspection.  
Well is TA.  
Battery & ALL equipment is Shut-down.  
Centralized Battery serves 5 Location IDs (305921, 305863, 305922, 306481, 306556).  
Refer to FIR #696100376 and/or Location ID #305921 for Battery / Facility, Equipment info.

Follow-up to FIR #689300443 dated 12/01/2017.  
1 of 1 Corrective Actions from previous FIR has been addressed.  
1.) LTSI well had no MIT on record. Form 21 #401906743 indicates MIT done: 01/14/2019. (Approval Pending).  
SI/TA well per variance Doc #401474555. (NOBLE).

2 - Corrective Actions identified on this FIR.  
1.) Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See photo #1.  
Remove unused equipment at wellsite. Comply w/ Rule 603.f.  
2.) SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.  
Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.		
Corrective Action:	Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).		Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See photo #1.		
Corrective Action:	Remove unused equipment at wellsite. Comply w/ Rule 603.f.		Date: 04/05/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Refer to FIR #696100376 and/or Location ID #305921 for additional Fencing info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type:		#	corrective date
Comment:	Refer to FIR #696100376 and/or Location ID #305921 for additional Equipment info.		
Corrective Action:			Date:
Type: Other		# 1	
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:			Date:
Type: Other		# 1	
Comment:	Wellhead w/ master valve, casing head & valves.		

Corrective Action:	Date:
--------------------	-------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.490481,-104.832546

Comment: [Centralized Battery serves 5 Location IDs \(305921, 305863, 305922, 306481,306556\). Refer to FIR #696100376 and/or Location ID #305921 for Tanks & Berms info.](#)

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:	Date:
--------------------	-------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 283713 Type: WELL API Number: 123-23684 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA. Well disconnected from flowline.  
Form 4 #401920936 indicates TA since 11/30/2018. (Approval Pending).  
LTSI well had no MIT on record from prev. FIR.  
Form 21 #401906743 indicates MIT done: 01/14/2019. (Approval Pending).  
SI/TA well per variance Doc #401474555. (NOBLE).  
This addresses CA from prev. FIR.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100381	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754216">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754216</a>