

Inspection Photos  
Location Name: Orr E 19-05  
Location ID: 310432



Photo 1: Wellhead



Photo 2: Tank Battery